

Legend: Deterioration Mapping (Based on ICOMOS - ISCS Illustrated Glossary 2008)

Crack & Deformation

Crack

Biological Colonisation

Biological Colonisation

Detachment

Delamination including Exfoliation

Disintegration including Powdering

Scaling including Flaking

Features Induced By Material Loss

Alveolisation

Back Weathering

Erosion including Differential Erosion

Mechanical Damage

Missing Part

Discoloration & Deposit

Crust

Deposit

Patina

Others

Accretions

Accretions

Cement Rendering

Metal Inserts

Paint

Plastering

Previous Interventions

Services, Cables on Surface

Thick Concrete Layer

St Publius Street

Biological growth to be addressed

Apertures to be repainted

Open/defective joints to be repointed

Elevation onto parvis  
Scale 1:100

04

Biological growth to be addressed

Apertures to be repainted

Deposits to be cleaned

Proposed security grilles, metal, painted white

Metal inserts to be removed

St Thomas Street

Apertures to be repainted

Previous replacement stone to be removed and intervention carried out more sensitively

Deteriorated stone to be repaired/replaced

Plastic pipe to be replaced with cast iron pipe

Open/defective joints to be repointed

Door to be replaced

Deteriorated/damaged balusters to be replaced

Grilles to be replaced

Plasters to be removed

SALA SAN PUBLIUS

Scale 1:100

Elevation on St Publius Street  
Scale 1:100

03

NOTES:

Block Plan NTS

Property dates to before 1967

REVISION MARK			
Atelier Periti			
Conservation, Architecture and Civil Engineering			
Chantal, 5 Zammit Hammet Street, Balzan GZN 1111			
Tel: 7942 9875			
THIS DRAWING REMAINS THE PROPERTY OF ATTELIER PERITI AND MUST NOT BE USED OR COPIED WITHOUT WRITTEN PERMISSION			
TITLE			
FACADE OVERLOOKING ST PUBLIUS STREET WITH PROPOSED INTERVENTIONS			
ST PUBLIUS PARISH CHURCH FLORIANA			
-			
PROJECT ARCH	M.A.	LOC. NO	-
CHECKED	-	CAD REFERENCE	-
DRAWN BY	-		
SCALE	1:100	DRAWING NO.	315/20/14
DATE	30/05/2020		
JOB NO	315/20		

Page 1 of 1